

Product Safety Recall



DeWalt Midland Gumboots

Sold at Bunnings between June 2019 and July 2020

DEFECT Steel toe cap may be missing in some boots.

HAZARD If the steel cap is missing, the boots will not protect the toes from being crushed by heavy objects landing on the foot.

WHAT TO DO Consumers should inspect their boots to check if they have the steel toe caps. This can be done by pressing down on the ribbed toe guard at the front of each boot. If the steel cap is absent, the toe of the boot will compress.

If the steel cap is missing, contact Mayo Hardware to arrange for the boots to be returned and replaced.

For further information, contact Mayo Hardware on 09 415 6240 or email dewalt@mayohardware.com.au

Importer: Mayo Hardware

See www.recalls.govt.nz for
other New Zealand consumer product recalls