


ELECTRICAL SAFETY RECALL

All Akai, Moretti and Click brand oil column heaters



Which heaters are affected

The following models are affected by the recall.

Model	Bunnings code	Batch/date code
MO-WWM6-5	F/L: 4441771	12/16 ←
RWOF-11T	F/L: 4441743	10554
CDFP3-5	F/L: 4441770	12/16
MC35B2	F/L: 4441019	12/16
MO-WWM6-7	F/L: 4441773	12/16
MO-WWM6-11	F/L: 4441774	12/16
OFH-07LCD	F/L: 8902305	10665
YL-B12-7	F/L :8902505	10659
OFH-11LCD	F/L :8902525	10663

Identification

The model number & batch code are marked on the rating label which is located on the front panel of the heater. The recalled heaters were sold by Bunnings from 1 January 2017 to April 2017.

Defect

A manufacturing defect may cause the heater to rupture when turned on allowing hot oil to spray out.

Hazard

Risk of fire and risk of scalding and burns.

Action Required

Customers should cease using this heater immediately and return to any Bunnings store for a full refund.

Contact Details

For further information, please call **0800 561 109** or go to www.bunnings.co.nz to locate your nearest Bunnings store.

**See www.recalls.govt.nz for
New Zealand product recall information**