

Product Safety Recall



Makita (Australia) Pty Ltd ABN:57 001 117 335
2 Litton Close, Pemulwuy NSW 2145
Tel: 1300 361 690 www.makita.com.au



Makita Brushcutter Model Number

EM2600L 25.7cc 2 Stroke Brushcutter Loop Handle

EM2600U 25.7cc 2 Stroke Brushcutter U Handle

With a production date range between 16.01 (2016 January) and 17.06 (2017 June)
(Sold between January 2016 & 15th September 2017)

Location of the Production Date



Model Number

Production Date

In the interest of user safety, Makita (Australia) Pty Ltd is undertaking a recall of our EM2600L and EM2600U brushcutters due to a potential leaking fuel tank.

Defect: The fuel tank seal & fuel lines may leak petrol.

Hazard: Leaking petrol is a fire hazard.

What to do: Check the model and production date of your brushcutter (see illustration on left).

Location of the Serial Number



Model Number

Serial Number

Affected product can be identified on our dedicated website www.makita.com.au/recall or alternatively you can contact Makita on 1300 361 690 between 8am and 5pm (AEST).

If the model and production date of your brushcutter is within the affected range – stop using it immediately and carefully drain the fuel tank.

Take the tool to your nearest Makita Service Centre for a no charge replacement of the fuel tank seal & fuel lines, or contact us on 1300 361 690 and we can assist in arranging the repair at your closest Authorised Service Agent.

**See productsafety.gov.au for
Australian product recall information**

Product Safety Recall



Makita (Australia) Pty Ltd ABN:57 001 117 335
2 Litton Close, Pemulwuy NSW 2145
Tel: 1300 361 690 www.makita.com.au



Makita Brushcutter Model Number

ER2600L 25.7cc 2 Stroke Line Trimmer
Loop Handle, Bent Shaft

With a production date range between 16.01 (2016 January) and 17.06 (2017 June)
(Sold between January 2016 & 15th September 2017)

Location of the Production Date



Model Number

Production Date

Location of the Serial Number



Model Number

Serial Number

In the interest of user safety, Makita (Australia) Pty Ltd is undertaking a recall of our ER2600L brushcutter due to a potential leaking fuel tank.

Defect: The fuel tank seal & fuel lines may leak petrol.

Hazard: Leaking petrol is a fire hazard.

What to do: Check the model and production date of your brushcutter (see illustration on left).

Affected product can be identified on our dedicated website www.makita.com.au/recall or alternatively you can contact Makita on 1300 361 690 between 8am and 5pm (AEST).

If the model and production date of your brushcutter is within the affected range – stop using it immediately and carefully drain the fuel tank.

Take the tool to your nearest Makita Service Centre for a no charge replacement of the fuel tank seal & fuel lines, or contact us on 1300 361 690 and we can assist in arranging the repair at your closest Authorised Service Agent.

**See productsafety.gov.au for
Australian product recall information**